

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 12719-20

Dated: 23/05/2025

It is certified that the existing building **Dhauladhar Public School** (name of the building or premises) at ...**Vill-Majhotu PO-Barotiwala Teh- Baddi Distt- Solan(HP)**... (address) is having block(s)/Floor(s) as per details below:


| Detail of Block(s) in school | Block (1)        | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|------------------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | Ground + 4 Floor |           |           |           |           |           |

The building is owned/occupied by....**Dhauladhar Education Foundation**.....(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of ....**Jr. Engineer HPPWD Sub Division Barotiwala**..... (Name of Department/Govt.) on...**21/01/2022**...(date of inspection) in the presence of.....**Assistant Engineer Baddi Sub Division HPPWD**.....(name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from...**28/01/2022**..... for a period of .....**27/01/2027**..... years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on **28/01/2022** at.. **Nalagarh Executive Engineer Nalagarh Division HPPWD Nalagarh**..by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : Munish Thakur

Designation : Assistant Engineer

Name & Address of Department/ Office: HPPWD

Assistant Engineer  
Baddi Sub-Division  
H.P.P.W.D. Baddi